

EAST Search History

Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L1	1	("6128560").PN.	US-PGPUB; USPAT; EPO; JPO	OR	OFF	2008/02/11 12:53
S1	3	("5600550" "6009369" "6486637").PN.	US-PGPUB; USPAT; EPO	OR	OFF	2008/02/07 16:26
S2	1	("20070069695").PN.	US-PGPUB; USPAT; EPO; JPO	OR	OFF	2008/02/07 16:31
S3	578	vehicle and (overheat temperature) same current same voltage same (abnormal\$4 anmonalous fail transient spike)	US-PGPUB; USPAT; EPO	OR	OFF	2008/02/08 14:25
S4	2905	(307/10.1).CQLS.	US-PGPUB; USPAT; EPO; JPO	OR	OFF	2008/02/08 14:25
S5	25	("20010010458" "20010011921" "20030034848" "20040017112" "20040150933" "20070132315" "4417201" "4463431" "4899152" "5619122" "5671149" "5801594" "5805403" "5875388" "5892408" "6040736" "6046551" "6191563" "6351718" "6441679" "6476682" "6591210" "6781341" "6853259" "7209401").PN.	US-PGPUB; USPAT; EPO	OR	OFF	2008/02/08 15:32
S6	10	("6131073").PN"	US-PGPUB; USPAT; EPO	OR	OFF	2008/02/08 15:35
S7	35316	vehicle and (overheat temperature) same current	US-PGPUB; USPAT; EPO	OR	OFF	2008/02/08 16:02
S8	2905	(307/10.1).CQLS.	US-PGPUB; USPAT; EPO; JPO	OR	OFF	2008/02/08 16:02

S9	237	S7 and S8	US-PGPUB; USPAT; EPO	OR	OFF	2008/02/08 16:02
S10	3	("5600550" "6009369" "6486637").PN.	US-PGPUB; USPAT; EPO	OR	OFF	2008/02/08 16:10
S11	13	("5600550").URFN.	USPAT	OR	OFF	2008/02/08 16:12
S12	74	voltage adj (sens\$4 detect\$4) same temperature adj (sens\$4 detect\$4) and vehicle and abnormality	USPAT	OR	OFF	2008/02/08 16:24
S13	11	voltage adj (sens\$4 detect\$4) same temperature adj (sens\$4 detect\$4) same abnormality and vehicle	USPAT	OR	OFF	2008/02/08 16:24
S14	13	("20030129457" "5850351" "6020717" "6104967" "6140820" "6252376" "6291972" "6486637" "6762590" "6803766" "6828798" "6919707").PN. OR ("7019488").URFN.	US-PGPUB; USPAT; USOCR	OR	OFF	2008/02/08 16:28
S15	1995	307/9.1	USPAT	OR	OFF	2008/02/08 16:41
S16	1133	power adj (line wire connection) with temperature	US-PGPUB; USPAT; EPO	OR	OFF	2008/02/08 16:51
S17	20	power adj (line wire connection) with temperature with (overheat abnormal\$4 anaomo\$4)	US-PGPUB; USPAT; EPO	OR	OFF	2008/02/08 16:52
S18	14111	overheat temperature adj abnormality	US-PGPUB; USPAT; EPO	OR	OFF	2008/02/08 16:59
S19	698	S18 with (wire connection line bus)	US-PGPUB; USPAT; EPO	OR	OFF	2008/02/08 16:59
S20	121	S19 and vehicle	US-PGPUB; USPAT; EPO	OR	OFF	2008/02/08 16:59
S21	1	"6486637".pn.	US-PGPUB; USPAT; EPO	OR	OFF	2008/02/08 17:01

S22	14476	(overheat temperature) same transient	US-PGPUB; USPAT; EPO	OR	OFF	2008/02/09 09:49
S23	350	(overheat temperature) same transient same voltage and vehicle	US-PGPUB; USPAT; EPO	OR	OFF	2008/02/09 09:49
S24	160	(overheat temperature) same transient same voltage same current and vehicle	US-PGPUB; USPAT; EPO	OR	OFF	2008/02/09 09:49
S25	4	("4024451" "5808453" "5866957" "6674657").PN.	US-PGPUB; USPAT; USOCR	OR	OFF	2008/02/09 10:25
S26	1	("5444595").PN.	US-PGPUB; USPAT; EPO	OR	OFF	2008/02/11 09:09
S27	18	(US-20070069695-\$ or US-20070103006-\$ or US- 20020118502-\$ or US- 20070016337-\$ or US- 20030105564-\$).did. or (US-6320275-\$ or US- 6989976-\$ or US- 6373671-\$ or US- 5600550-\$ or US- 7019488-\$ or US- 6377880-\$ or US- 6486637-\$ or US- 6127741-\$ or US- 7038430-\$ or US- 5898557-\$ or US- 6594129-\$ or US- 6770985-\$ or US- 6674657-\$).did.	US-PGPUB; USPAT	OR	OFF	2008/02/11 11:05
S28	1	S27 and (printed PCB)	US-PGPUB; USPAT	OR	OFF	2008/02/11 11:05

2/11/2008 12:53:39 PM

C:\Documents and Settings\mrutlandwallis\My Documents\EAST\Workspaces\10564600
Vehicle Temp and Overcurrent controller.wsp